



FIG. 5.1 Metallic resistance thermometers. The resistance vs. temperature characteristics of these sensors have a positive temperature derivative. Platinum resistance thermometers are highly reproducible and very popular for measurements above ~ 77 K. In the lower temperature range, below about 20 K, rhodium-iron resistance thermometers are more sensitive than platinum sensors. Both have excellent reproducibility.