



FIG. 9.16 U-bending beam for measuring strain effects on short samples (from ten Haken et al. 1995). The sample is soldered to the bending beam, and the backbone of the U is flexed by applying force to the two arms. Strain is measured by strain gauges bonded to the beam.